

ESR9850_Changelog

Release Date Feb 22, 2012

WEB version: 2.1.3

Firmware upgrade:

- ESR9850-APPS-V2-1-3-4.dlf
- ESR9850-KNL-V2-1-3-4.dlf

MD5 Checksum:

- APPS : d3b0d2733cfb25696b55a98c97470694
- KNL : 2b971a330aa042541e87717574d8e6f8

New Features

- N/A.

Problems Resolved:

- Solve the bug that ShieldsUP Port Scan test fail.

Change:

- N/A.